



Prun

On site, tanks and D-box have been installed and leveled. Trenches are being dug later. They are stripping top surface soils on D. Box are level, crown not yet arrived at the time of inspection. Invert: * taken at D. Box, 6.5" @ 11:30 AM. Trench Spacing: 10'. Trench Depth: 8'4", Material at 120 ft. 1 1/2" of ESL

1/3/18. *Quinn* L. E. H. S.

